

## Love Lane Cemetery Memorial Inspection Results

An inspection of all headstones in Love Lane Cemetery was undertaken on 26.9.23 but the Town Clerk and Groundsman. Following the inspection, the following graves were flagged as being in need of attention

### Action Priority

- 1 Immediate attention
- 2 Re-inspect 1 year
- 3 Re-inspect 5 years

Plot no	Name	Action required	Priority	Action Taken
36	Edge	Book loose on base	2	Repaired with firmabond 26.9.23
69	Jarvis	Slight movement	2	Monitor
70	Williams	Slight movement of upright	2	Monitor
85	Warner	Loose on base	2	Repaired with firmabond (redo repair first completed 7.6.19)
127	Lewis	Slight movement of upright	2	Monitor
130	Mary and Isaac hughes	Slight movement of upright	2	Monitor
150	Harper	Slight movement of upright	2	Monitor
163	Stokes	Significant movement	1	Sign on headstone and staked owner to be contacted Letter sent 27/9 17.11.23 not repaired
178	Rand	Movement of base	2	Repaired with firmabond 26.9.23
233	Hall	Slight movement of upright	2	Monitor (previous sealing with firmabond)
256	Dempster	Slight movement of top section low risk	2	Monitor
258	Roberts	Loose on upright	1	Stake Grave and Notice on grave Letter sent 27/9 Wenlock Stone booked to carry out work 24.10.23 <b>Not repaired 17.11.23</b>
273	Jones	Loose on upright	1	Stake Grave and Notice on grave Letter sent 27/9 <b>Not repaired 17.11.23</b>
277	Pemberton	Very loose	1	Stake grave and notice posted Letter sent 27/9 <b>Not repaired 17.11.23</b>
283	Magrath	Significant movement	1	Stake grave and notice posted Letter sent 27/9 <b>Repaired 17.11.23</b>

320	R. Thomas	Movement of upright on plinth	1	Stake grave and notice posted Repaired by owner 2021 Letter sent 27/9 <b>Repaired 17.11.23</b>
325	Thomson	Significant movement of upright on plinth (2021 monitor)	1	Stake Grave and notice posted Letter sent 27/9 <b>Not repaired 17.11.23</b>
339	Ludlow	Upright loose	1	Stake grave and notice posted Letter sent 27/9 <b>Repaired 17.11.23</b>
352	Bleakley	Slight movement round anchor engaging	2	Monitor
400	Wycherley	movement of upright	1	<i>Stake grave and notice posted on headstone</i> (Failed 2021 inspection owner to action repair) Letter sent 27/9 <b>Not repaired 17.11.23</b>
402	Wilson	Loose on upright	1	<i>Stake grave and notice posted</i> (Failed 2019 inspection repaired, monitor 2021) Letter sent 27/9 <b>Repaired 17.11.23</b>
405	Glassford/ Moncreif	Significant movement	1	<i>Stake Grave and notice posted</i> <b>Repaired 17.11.23</b>
446	Howells	Slight movement on upright	2	<i>Monitor</i>

#### Clerks Recommendation

As many graves are visited over the Christmas period further letters should be sent out and a new inspection of the graves in red take place in January.